

March 4, 2004

Van Kessler
Godfrey Conveyor Company, Inc. (Godfrey Marine)
4500 Middlebury Street
Elkhart, Indiana 46516

Re: 039-18705
First Administrative Amendment to
Part 70 039-8962-00267

Dear Van Kessler:

Godfrey Conveyor Company, Inc. (Godfrey Marine) was issued a Title V permit on March 31, 2000 for a stationary fiberglass and aluminum boat manufacturing operation. A letter requesting a change was received on February 3, 2004. Pursuant to the provisions of 2-7-11(a)(7) "revises descriptive information where the revision will not trigger a new applicable requirement or violate a permit term", the permit is hereby administratively amended as follows:

A dust collection system is being added to a grinding booth. The system will have no direct exhaust exit points. This will improve air quality and particulate control. The system will replace dry filters being used at the booth. There is no increase in emissions related to this change.

Section A.2 and the description in Section D.1 will be changed as follows:

- (3) One (1) grinding booth, located in Plant 6, with a maximum capacity of 450 pounds of flange material processed per hour, equipped with ~~dry filters for particulate matter control, exhausting to two (2) stacks, identified as EF6-2 and EF6-3~~ **a close looped Frees dust collection system with no direct exhaust exit points.**

Condition D.1.9 will be amended as:

The cyclone ~~and dry filters for PM control~~ shall be in operation at all times when the ~~grinding booth,~~ fiberglass operations and the four (4) woodworking machines are in operation.

Condition D.1.10 will be amended as:

- (a) ~~Weekly inspections shall be performed to verify the placement, integrity and particle loading of the filters. The Compliance Response Plan shall be followed whenever a condition exists which should result in a response step. Failure to take response steps in accordance with Section C - Compliance Monitoring Plan - Failure to Take Response Steps shall be considered a violation of this permit.~~

- ~~(b)~~ Monthly inspections shall be performed of the coating emissions from the stack and the presence of overspray on the rooftops and the nearby ground, weather permitting. The Compliance Response Plan for this unit shall contain troubleshooting contingency and response steps for when a noticeable change in overspray emission, or evidence of overspray emission is observed. The Compliance Response Plan shall be followed whenever a condition exists which should result in a response step. Failure to take

response steps in accordance with Section C - Compliance Monitoring Plan - Failure to Take Response Steps shall be considered a violation of this permit.

~~(c)~~

(b)

Condition D.1.12 will be amended as follows:

- (c) To document compliance with Condition D.1.10, the Permittee shall maintain a log of ~~weekly overspray observations~~, monthly inspections, and those additional inspections prescribed by the Preventive Maintenance Plan.

All other conditions of the permit shall remain unchanged and in effect. Please attach a copy of this amendment and the following revised permit pages to the front of the original permit.

This decision is subject to the Indiana Administrative Orders and Procedures Act - IC 4-21.5-3-5. If you have any questions on this matter, please contact Vince Kong, at (800) 451-6027, press 0 and ask for Vince Kong or extension 4-3350, or dial (317) 234-3350.

Sincerely,

Original signed by
Paul Dubenetzky, Chief
Permits Branch
Office of Air Quality

Attachments

vk

cc: File - Elkhart County
U.S. EPA, Region V
Elkhart County Health Department
Northwest Regional Office
Air Compliance Section Inspector - Paul Karkiewicz
Compliance Data Section
Administrative and Development