



INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

Mitchell E. Daniels Jr.
Governor

Thomas W. Easterly
Commissioner

100 North Senate Avenue
Indianapolis, Indiana 46204
(317) 232-8603
Toll Free (800) 451-6027
www.idem.IN.gov

Gordon Stewart
Anchor Glass Container Corporation
3101 West Dr. Martin Luther King Jr. Blvd., Suite 301
Tampa, FL 33607-6204

September 9, 2009

Re: Response to Review Request No. 029-28390-00007
Permit Status Evaluation
Plant ID: 029-00007

Dear Mr. Stewart:

Anchor Glass Container Corporation was issued a Part 70 Operating Permit First Renewal No. T029-18871-00007 on January 23, 2007 for a stationary glass container manufacturing operation located at 200 West Belleview Drive, Lawrenceburg, Indiana 47025. On August 28, 2009, the Office of Air Quality (OAQ) received a request from the source for review of permit modification level to rebrick the existing permitted glass furnace, identified as Furnace #2, and to change the design of the existing permitted forming machines used for mold swabbing operations.

Rebricking of the Furnace #2

Pursuant to 40 CFR 60.292(c), rebricking of a glass furnace is not considered reconstruction under New Source Performance Standard (NSPS). Therefore, the rebricking of the furnace #2 is not a reconstruction under NSPS and 326 IAC 1-2-65 (Reconstruction).

There is no emission increase as the throughput capacity of the furnace has not been changed. Therefore, it is not a modification under NSPS and 326 IAC 1-2-42 (Modification).

Design changes of the forming machines

There is no emission increase due the design changes of the forming machines, explained as follows: The emissions from the forming operations are exclusively due to the application of mold lubricant (known as swab dope). The consumption of the swab dope correlates to the number of cavities in the forming machines. Since there is no increase in the number of cavities due to the design changes of the forming machines, the emissions are not increased.

There is no modification approval or permit change required due to the rebricking of the Furnace #2 and design changes of the forming machines.

All conditions of the permit shall remain unchanged and in effect. For additional information about air permits and how the public and interested parties can participate, refer to the IDEM's Guide for Citizen Participation and Permit Guide on the Internet at: www.idem.in.gov

This decision is subject to the Indiana Administrative Orders and Procedures Act - IC 4-21.5-3-5. If you have any questions on this matter, please contact Mehul Sura, of my staff, at 317-233-6868 or 1-800-451-6027, and ask for extension 3-6868.

Sincerely,

Chrystal A. Wagner, Section Chief
Permits Branch
Office of Air Quality

mns

cc: File - Dearborn County
Dearborn County Health Department
U.S. EPA, Region V
Compliance and Enforcement Managers
Permits Administration and Support

Mail Code 61-53

IDEM Staff	GHOTOPP 9/9/2009 Anchor Glass Container Corp 029-28390-00007 Final		Type of Mail: CERTIFICATE OF MAILING ONLY	AFFIX STAMP HERE IF USED AS CERTIFICATE OF MAILING
Name and address of Sender		Indiana Department of Environmental Management Office of Air Quality – Permits Branch 100 N. Senate Indianapolis, IN 46204		

Line	Article Number	Name, Address, Street and Post Office Address	Postage	Handing Charges	Act. Value (If Registered)	Insured Value	Due Send if COD	R.R. Fee	S.D. Fee	S.H. Fee	Rest. Del. Fee	Remarks
1		Greg Dowler Anchor Glass Container Corp 401 E Jackson St, Ste 2800 Tampa FL 33602 (Source CAATS)										
2		Dearborn County Commissioner 215 B West High Street Lawrenceburg IN 47025 (Local Official)										
3		Lawrenceburg City Council and Mayors Office 212 Walnut St. Lawrenceburg IN 47025 (Local Official)										
4		Dearborn County Health Department 215-b W. Hight St, County Admin Building Lawrenceburg IN 47025-1910 (Health Department)										
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												

Total number of pieces Listed by Sender	Total number of Pieces Received at Post Office	Postmaster, Per (Name of Receiving employee)	The full declaration of value is required on all domestic and international registered mail. The maximum indemnity payable for the reconstruction of nonnegotiable documents under Express Mail document reconstructing insurance is \$50,000 per piece subject to a limit of \$50, 000 per occurrence. The maximum indemnity payable on Express mil merchandise insurance is \$500. The maximum indemnity payable is \$25,000 for registered mail, sent with optional postal insurance. See Domestic Mail Manual R900, S913, and S921 for limitations of coverage on inured and COD mail. See International Mail Manual for limitations o coverage on international mail. Special handling charges apply only to Standard Mail (A) and Standard Mail (B) parcels.
4			